



TO INFORM YOU

PRODUCT
SUPPORT
BULLETIN # 496

TO: AUTHORIZED *portable electric tool* SERVICE STATIONS
factory SERVICE CENTERS





DATE: July, 2009

TOOL(S) \ PRODUCT(S) AFFECTED: 0719-20, 0719-50, 0819-50, 6515-20 (971D series only), 6515-50 (971D series only), 6519-22, 6520-21, 6523-21, 6523-51, 6523-55, 6536-21, 6536-51, 6538-21 SAWZALL®

SUBJECT: 45-12-0700, 45-12-0710 & 45-12-0999 Gear Case Insulator Boot

A running change has been made to the 45-12-0700, 45-12-0710 & 45-12-0999 Gear Case Insulator Boot adding material (see illustrations).

We recommend a no-charge replacement of a gear case insulator boot on all Sawzalls (0719-series, 6515-series, 6519-22, 6520-series, 6523-series, 6536-series & 6538-21) received with a damaged boot or upon a customer's request.

Gear Case Insulator Boot	where-used
	45-12-0700 Insulator Boot ORBITAL SUPER SAWZALL® 6523-21, 6523-51, 6523-55, 6536-21, 6536-51, 6538-21
	45-12-0710 Insulator Boot ORBITAL SAWZALL® 6520-21
	45-12-0999 Insulator Boot V18 – V28 CORDLESS SAWZALL® 0719-20, 0719-50, 0819-50, SAWZALL® PLUS 6515-20 (971D series only), 6515-50 (971D series only), 6519-22
 utility knife cut original Insulator Boot "off" and discard	

This bulletin is for informational purposes. PLEASE NOTE ON SERVICE PARTS LIST: 54-40-1603, 54-40-5180, 54-40-5181, 54-40-5182, 54-40-5183, 54-40-7000, 54-40-7001, 54-40-7560, 54-40-7561, 54-40-7562, 54-40-7563, 54-40-7570, 54-40-7580, 54-40-7581, 54-40-7582, 54-40-7583, 54-40-7590, 54-40-7591, 54-40-7592, 55-40-0840, 55-40-1603, 55-40-7010, 55-40-7011, 55-40-7560, 55-40-7580, 55-40-7600